

METHOD OF ASSEMBLY OF A WEDGE THERMAL
INTERFACE TO ALLOW EXPANSION AFTER ASSEMBLY

Joseph M. White et al.

200300041-1

1/9

FIG. 1A








FIG. 1B




2/9



3/9



4/9



5/9

FIG. 4B







FIG. 4C





7/9

FIG. 6



8/9




FIG. 5C




FIG. 7

